Graco 244194 Replacement Pump Repair Kit

Regular Price
$144.93 Special Price
$130.44
INCL. GST

Product Images

Short Description

Graco 244194 Replacement Pump Repair Kit will suit a wide range of Graco airless sprayers from 190, 390, 395, 490, 495, 595 & 3400 airless sprayers, LineLazer ES1000 and 3400 line markers. Service kit includes all seals, v-packings and balls to service the fluid pump.

Description

Graco 244194 Replacement Pump Repair Kit includes all seals, v-packings and balls to service the fluid pump. Precision made in the USA.

Graco 244194 Replacement Pump Repair Kit will suit a wide range of Graco airless sprayers from 190, 390, 395, 490, 495, 595 & 3400 airless sprayers, LineLazer ES1000 and 3400 line markers.

Graco 244194 Replacement Pump Repair Kit can be used in both standard and pro-connect endurance pumps.

Precision made in the USA to the highest quality for maximum performance.

Atomex Part No. AX/G244-194

Replaces Graco Part No. 244194

Same as Graco Part No. 18B260

Visit our product download centre for manuals & spare parts

Additional Information

Brands	Graco
Equipment Type	Airless Sprayers, Line Marking Machines
Machine Type	Electric 240V, Petrol, Battery
Machine Model Number	190 PC Express, 390 PC, 395 PC PRO, 490 PC PRO, 495 PC PRO, 595 PC PRO, 650 PC PRO, 395 PC FinishPro, 595 PC FinishPro, 390, 395 Ultra, 490 UltraMax II, 495 UltraMax II, 595 UltraMax II, 390 FinishPro, 395 FinishPro, 595 FinishPro, 3400 LineLazer, 3400 GMax II, ES1000 LineLazer V
OEM	Aftermarket