



# Speeflo 930-050 Replacement 930 Series Outlet Filter Service Kit

**\$58.45**  
**INCL. GST**

## Product Images



## Short Description

Speeflo 930-050 Replacement 930 Series Outlet Filter Service Kit can be used with Speeflo, Titan and Wagner 930 series outlet filter manifolds.



## Description

---

Speeflo 930-050 Replacement 930 Series Outlet Filter Service Kit can be used with Speeflo, Titan and Wagner 930 series outlet filter manifolds.

Replaces Titan Part No. 930-050

Replaces Wagner Part No. 930-050

### **Kit Includes:**

1 x 920-006 Thick Gasket

1 x 920-070 Thin Gasket

1 x 891-193 O Ring

1 x 920-020 Spring

### **Models of airless sprayers that use this outlet filter repair kit -**

#### **Speeflo Models:**

All PowrTwin Gas Models 4900, 6900, 8900,12000

All PowrLiner Line Markers 6000, 6900, 8900

Admiral Air Driven Pumps

#### **Titan Models:**

All PowrLiner Line Markers 4955, 6955, 8955, ProMark 200

#### **Wagner Models:**

Wagner Heavy Coat HC920, HC940, HC960

Wagner Heavy Coat HC950, HC950, HC970

Wagner Line Marker LC820, LC840, LC860, LC860SP

Made to the highest quality in the USA.

## Additional Information

---

Brands

Titan, Wagner

