



# Graco 287031 FTx II & Contactor II Replacement Airless Spray Gun Repair Kit

Regular Price

**\$153.34** Special Price

**\$138.01**

**INCL. GST**

## Product Images



## Short Description

Atomex 287031 replacement Airless Spray Gun repair kit for the Contractor II & FTx-II airless spray guns.

Made in the USA.

## Description

---

Airless spray guns will require periodic service, over time and after many trigger pulls the carbide ball at the end of the needle will wear against seat on the diffuser. This will cause paint to leak or spit from the tip when you let go of the trigger.

Replacing the needle and diffuser (gun kit) is a normal part of airless sprayer maintenance and should be done as required. Keep a spare kit in your tool box to reduce down time on the job.

### **Gun Repair Kit will suit the following model guns –**

Contractor II Models: 246020, 246221, 246222, 246224, 246225, 246434, 246538, 824987

FTx-II Gun Models: 246230, 246231, 246232, 246233, 246234, 246235, 246435, 246539, 246540

Atomex Part No. AX/G287-031

Replaces Graco Part No. 287031

Replaces Bedford Part No. 20-2701

This gun repair kit will fit into guns that look like this



## Additional Information

Brands	Graco
Equipment Type	Airless Sprayers
Machine Type	Airless Spray Guns
Machine Model Number	Contractor II/FTx II Gun
OEM	Aftermarket

