



Graco 235474 Flex Gun Plus Replacement Airless Spray Gun Repair Kit

Regular Price

\$204.77 Special Price

\$184.29

INCL. GST

Product Images



Short Description

Atomex 235474 replacement Airless Spray Gun repair kit for the Graco Silver Gun Plus and Flex Gun Plus airless spray guns. Made in the USA.

Description

Airless spray guns will require periodic service, over time and after many trigger pulls the carbide ball at the end of the needle will wear against seat on the diffuser. This will cause paint to leak or spit from the tip when you let go of the trigger.

Replacing the needle and diffuser (gun kit) is a normal part of airless sprayer maintenance and should be done as required. Keep a spare kit in your tool box to reduce down time on the job.

Gun Repair Kit will suit the following model guns -

Graco Silver Gun Plus: 235460,235461,235462,235463, 235464, 236531, 237695, 238591, 238966

Graco Flex Gun Plus: 235457, 235458, 235459, 237691, 248157, 246468, 246240, 243283

Atomex Part No. AX/G235-474

Replaces Graco Part No. 235474

Replaces Bedford Part No. 20-1930

This gun repair kit will fit into guns that look like this





Additional Information

Brands	Graco
Equipment Type	Airless Sprayers, Line Marking Machines
Machine Type	Petrol, Airless Spray Guns, Battery
Machine Model Number	Silver Plus & Flex Plus Guns, 3400 LineLazer, 3900 LineLazer V, 5900 LineLazer V, 200HS LineLazer V, 250DC LineLazer V, 250SPS LineLazer V, ES1000 LineLazer V, ES2000 LineLazer V, 130HS LineLazer IV, 130HS LineLazer V, 3900 LineLazer IV, 5900 LineLazer IV, 200HS LineLazer IV, 250SPS LineLazer IV
OEM	Aftermarket

