



# Graco 248837 XTR5/XTR7 Replacement Airless Spray Gun Repair Kit

**\$163.63**  
**INCL. GST**

## Product Images



## Short Description

Atomex 248837 replacement Airless Spray Gun repair kit for XTR5 & XTR7 airless spray guns. Made in the USA.

## Description

---

Airless spray guns will require periodic service, over time and after many trigger pulls the carbide ball at the end of the needle will wear against seat on the diffuser. This will cause paint to leak or spit from the tip when you let go of the trigger.

Replacing the needle and diffuser (gun kit) is a normal part of airless sprayer maintenance and should be done as required. Keep a spare kit in your tool box to reduce down time on the job.

### **Gun Repair Kit will suit the following model guns -**

Graco XTR7: 248609, 248610, 248611, 248612, 248613, 248614, XTR700, XTR701, XTR702, XTR703, XTR704, XTR705, XTR706

Graco XTR5: XTR500, XTR501, XTR502, XTR503, XTR504, XTR505, XTR510

Atomex Part No. AX/G248-837

Replaces Graco Part No. 248837

This gun repair kit will fit into guns that look like this



## Additional Information

---

Brands	Graco
Equipment Type	Airless Sprayers
Machine Type	Airless Spray Guns
Machine Model Number	XTR5/XTR7 Gun
OEM	Aftermarket

