




# Wagner 0277943 HVLP Gun Repair Kit

**\$87.47**  
**INCL. GST**

## Product Images



## Short Description

Wagner 0277943 HVLP Gun Repair Kit will suit all Capspray, Wagner & Titan Maxum II & NBC HVLP guns.

## Description

---

Wagner 0277943 HVLP Gun Repair Kit is used for regular/periodic service of Capspray, Wagner & Titan Maxum II & NBC HVLP guns.

### Wagner 0277943 HVLP Gun Repair Kit includes -

Front air valve seal	Wagner Part No. 0277486
Rear air valve seal	Wagner Part No. 0275501
Needle packing	Wagner Part No. 0275579
Air control valve o-ring (2)	Wagner Part No. 9871049
Check valve assembly	Wagner Part No. 0277482
Check valve tube short	Wagner Part No. 0276248
Check valve tube long	Wagner Part No. 0277483
Cup gasket	Wagner Part No. 0277495

Regular service and cleaning of your HVLP spray gun will reduce downtime or problems on the job.

Wagner Part No. 0277943

---

[Click here to see the full range of Wagner Maxum II HVLP Spare Parts](#)

AA Spray stock a full range of HVLP guns, fluid sets, check valves, filters and hoses to suit all models of Graco & Wagner HVLP Turbine Sprayers with fast delivery Australia wide.

## Additional Information

---

Brands	Wagner
Equipment Type	HVLP Turbines
Machine Type	Electric 240V
Machine Model Number	Maxum II, FC9900 Plus, CS8100, SoftSpray 2600
OEM	Original Part

