



# Graco 248212 Replacement Pump Repair Kit

Regular Price

**\$186.12** Special

Price

**\$167.51**

**INCL. GST**

## Product Images



## Short Description

---

Graco 248212 Replacement Pump Repair Kit will suit Graco 695/795 UltraMax II airless sprayers, Gmax II 3900 petrol airless sprayers, LineLazer ES2000 and 3900 line marking machines. Service kit includes all seals, v-packings and balls to service the fluid pump.

## Description

---

Graco 248212 Replacement Pump Repair Kit includes all seals, v-packings and balls to service the fluid pump. Precision made in the USA.

Graco 248212 Replacement Pump Repair Kit will suit Graco 695/795 UltraMax II airless sprayers, Gmax II 3900 petrol airless sprayers, LineLazer ES2000 and 3900 line marking machines.

Graco 248212 Replacement Pump Repair Kit can be used in both standard and pro-connect endurance pumps.

Precision made in the USA to the highest quality for maximum performance.

Atomex Part No. AX/G248-212

Replaces Graco Part No. 248212

---

[Visit our product download centre for manuals & spare parts](#)

## Additional Information

---

Brands	Graco
Equipment Type	Airless Sprayers, Line Marking Machines
Machine Type	Electric 240V, Petrol, Battery
Machine Model Number	3900 LineLazer V, 695 UltraMax II, 795 UltraMax II, 3400 GMax II, 3900 GMax II, ES2000 LineLazer V, 3900 LineLazer IV
OEM	Aftermarket

