



# Graco 248213 Replacement Pump Repair Kit

Regular Price

**\$215.99** Special  
Price

**\$194.39**

**INCL. GST**

## Product Images



## Short Description

---

Graco 248213 Replacement Pump Repair Kit will suit Graco 1095 UltraMax II airless sprayers, Gmax II 5900 petrol airless sprayers and LineLazer 5900 line marking machines. Service kit includes all seals, v-packings and balls to service the fluid pump.

## Description

Graco 248213 Replacement Pump Repair Kit includes all seals, v-packings and balls to service the fluid pump. Precision made in the USA.

Graco 248213 Replacement Pump Repair Kit will suit Graco 1095 UltraMax II airless sprayers, Gmax II 5900 petrol airless sprayers and LineLazer 5900 line marking machines.

Graco 248213 Replacement Pump Repair Kit can be used in both standard and pro-connect endurance pumps.

Precision made in the USA to the highest quality for maximum performance.

Atomex Part No. AX/G248-213

Replaces Graco Part No. 248213

Can be used in place of Graco Part No. 17K162

[Visit our product download centre for manuals & spare parts](#)

## Additional Information

Brands	Graco
Equipment Type	Airless Sprayers, Line Marking Machines
Machine Type	Electric 240V, Petrol
Machine Model Number	5900 LineLazer V, 1095 UltraMax II, 5900 GMax II, 5900 LineLazer IV
OEM	Aftermarket

