



Wagner T9080.00 Zip 52 Service Repair Kit OEM

Regular Price

\$675.00 Special Price

\$607.50

INCL. GST

Product Images



Short Description

Wagner T9080.00 Zip 52 Service Repair Kit includes diaphragms, balls, seats, PTFE seals, bushing guides & air valve seals to rebuild your Zip 52 pump. Made in Germany OEM repair kit.

Description

Wagner T9080.00 Zip 52 Service Repair Kit includes diaphragms, balls, seats, PTFE seals, bushing guides & air valve seals to rebuild your Zip 52 pump.

Diaphragm pumps will require periodic service where the pump needs to be overhauled. The Wagner T9080.00 Zip 52 Service Repair Kit will give you everything needed to strip, clean and re-build the pump. Take care not damage the pressure cover gasket and change over valve gasket as these items are not included in the kit.

We recommend to read the Wagner Zip 52 manual before servicing the pump.

Made in Germany.

Wagner Part No. T9080.00

[Visit our product download centre for manuals & spare parts](#)

Additional Information

Brands	Wagner
Equipment Type	Double Diaphragm Pumps
Machine Type	Pneumatic
Machine Model Number	Zip 52
OEM	Original Part

