



Graco 240517 Replacement Piston Rod

\$689.69
INCL. GST

Product Images



Short Description

Graco 240517 Replacement Piston Rod will suit standard Graco 1095 UltraMax II airless sprayers, Gmax II 5900 petrol airless sprayers and LineLazer 5900 line marking machines.

Description

Graco 240517 Replacement Piston Rod will suit standard Graco 1095 UltraMax II airless sprayers, Gmax II 5900 petrol airless sprayers and LineLazer 5900 line marking machines.

When replacing packing seals on your pump inspect the piston rod for wear, the piston rod shaft must be true, straight and have no wear marks, ripples or elongated scratches. Any wear or damage to the piston may cause the pump to leak externally or internally and will certainly reduce the life of your new packing seals.

Graco 240517 Replacement Piston Rod can only be used in standard pumps, the rod can not be used in Graco Pro-Contractor pumps.

Precision made in the USA to the highest quality for maximum performance.

Atomex Part No. AX/G240-517

Replaces Graco Part No. 240517

Replaces Graco Part No. 248207

[Visit our product download centre for manuals & spare parts](#)

Additional Information

| | |
|----------------------|---|
| Brands | Graco |
| Equipment Type | Airless Sprayers, Line Marking Machines |
| Machine Type | Electric 240V, Petrol |
| Machine Model Number | 5900 LineLazer V, 1095 UltraMax II, 5900 GMax II, 5900 LineLazer IV |
| OEM | Aftermarket |

