



Graco 243222 Replacement Pressure Transducer

\$187.00
INCL. GST

Product Images



Short Description

Graco 243222 Replacement Pressure Transducer will fit the most Graco electric and petrol driven airless sprayers. A faulty pressure transducer may produce an E=02 or E=03 error code on your display and will need to be replaced.

Description

Graco 243222 Replacement Pressure Transducer is used in a wide variety of Graco electric and petrol airless sprayer models. The pressure transducer connects between the high pressure filter and the control board. The transducer is designed to send a signal to the control board which uses this information to know when the sprayer has reached the maximum pressure.

Faulty transducers can cause the following error codes to appear in you digital display -

E=02 (High pressure signal from transducer)

E=03 (Transducer failure or connection error)

Faulty transducers can also allow your machine to run past the maximum pressure of 3300psi and not stop. Machines that over pressurise can be dangerous causing the paint hose to burst or other component damage such as pump or drain valve.

Transducer failure in Graco airless sprayers is a common occurrence and transducers are not serviceable they must be replaced.

Atomex Part No. AX/G243-222

Replaces Graco Part No. 243222

[Visit our product download centre for manuals & spare parts](#)

Additional Information

Brands	Atomex, Graco
Equipment Type	Airless Sprayers
Machine Type	Electric 240V, Petrol
Machine Model Number	395 PC PRO, 490 PC PRO, 495 PC PRO, 595 PC PRO, 650 PC PRO, 395 PC FinishPro, 595 PC FinishPro, 395 Ultra, 490 UltraMax II, 495 UltraMax II, 595 UltraMax II, 390 FinishPro, 395 FinishPro, 595 FinishPro, 695 UltraMax II, 795 UltraMax II, 1095 UltraMax II, 3400 GMax II, 3900 GMax II, 5900 GMax II, 7900 GMax II, 5900HD Gmax II, 7900HD Gmax II, Mark V TexSpray
OEM	Aftermarket

