



Wagner 0394942 Service Repair Kit for AC4600 Air Coat Spray Gun

Regular Price

\$557.00 Special Price

\$499.99

INCL. GST

Product Images



Short Description

Wagner 0394942 Service Repair Kit includes all parts needed to service the Wagner AC4600 AirCoat Air Assisted Airless Spray Gun.

Description

Wagner 0394942 Service Repair Kit includes all parts needed to service the Wagner AC4600 AirCoat Air Assisted Airless Spray Gun.

Air assisted airless spray guns will require periodic service, over time and after many trigger pulls the carbide ball at the end of the needle will wear against seat on the diffuser. This will cause paint to leak or spit from the tip when you let go of the trigger.

Replacing the needle and diffuser is a normal part of spray gun maintenance and should be done as required. Keep a spare kit in your tool box to reduce down time on the job.

Made in Switzerland.

Wagner Part No. 0394942

[Visit our product download centre for manuals & spare parts](#)

Additional Information

Brands	Wagner
Equipment Type	Airless Sprayers
Machine Type	Air Assisted Airless Spray Guns
Machine Model Number	AC4600 AirCoat Gun
OEM	Original Part

