




Graco 248214 Kit Repair Intake Tube

\$94.60
INCL. GST

Product Images



Short Description

Graco 248214 Kit Repair Intake Tube is used on most Graco UltraMaxII 695/795 Hi-Boy models from about 2004 onwards. Intake tube includes the 118494 O-ring that is fitted to the male thread of the intake valve housing.

Description

Graco 248214 Kit Repair Intake Tube is used on most Graco UltraMaxII 695/795 Hi-Boy models from about 2004 onwards. Intake tube includes the 118494 O-ring that is fitted to the male thread of the intake valve housing.

Length of the tube is 230mm and uses a [1" Suction Filter](#)

Graco 248214 Kit Repair Intake Tube is used on the following models –

- 695 UltraMax II Hi-Boy (Part No. 248593, 248592)
- 695 UltraMax II Hi-Boy (Part No. 249685, 249686)
- 695 UltraMax II Hi-Boy (Part No. 258876, 258874, 258877)
- 695 UltraMax II Hi-Boy (Part No. 16X660, 16X812, 16Y639)
- 695 UltraMax II Hi-Boy (Part No. 17E610, 17E613, 17E614)
- 795 UltraMax II Hi-Boy (Part No. 249431, 248594)
- 795 UltraMax II Hi-Boy (Part No. 249963, 249687)
- 795 UltraMax II Hi-Boy (Part No. 258881, 258879, 258882)
- 795 UltraMax II Hi-Boy (Part No. 16X870, 16X813, 16Y895)
- 795 UltraMax II Hi-Boy (Part No. 17E616, 17E617, 17E619)
-

Graco Part No. 248214

[Visit our product download centre for manuals & spare parts](#)

Additional Information

Brands	Graco
Equipment Type	Airless Sprayers
Machine Type	Electric 240V
Machine Model Number	695 UltraMax II, 795 UltraMax II
OEM	Original Part

