




# **Graco 246174 Hydraulic Seal Repair Kit**

\$179.30 INCL. GST

#### **Product Images**





### **Short Description**

Graco 246174 Hydraulic Seal Repair Kit is for servicing hydraulic motors on GH series petrol airless sprayers up to GH675 and HS Series LineLazer IV & V line marking machines. Includes all 0-rings, seals & rod bearing seals.

#### **Description**

Graco 246174 Hydraulic Seal Repair Kit is for servicing hydraulic motors on GH series petrol airless sprayers up to GH675 and HS Series LineLazer IV & V line marking machines. Includes all 0-rings, seals & rod bearing seals.

#### Graco 246174 Hydraulic Seal Repair Kit will suit the following models -

- Graco 130HS LineLazer IV & V
- Graco 200HS LineLazer IV & V
- Graco 200DC LineLazer IV & V
- Graco 250SPS LineLazer IV & V
- Graco 250DC LineLazer IV & V
- Graco GH130 Petrol Airless Sprayer
- Graco GH200 Petrol Airless Sprayer
- Graco GH230 Petrol Airless Sprayer
- Graco GH300 Petrol Airless Sprayer
- Graco GH675 Petrol Airless Sprayer

•

The Graco Hydraulic Motors used on the GH and HS series pumps are very durable but after a number of years the seals in the hydraulic motor will wear and need to be replaced.

Symptoms of worn seals would be if the pump intermittently cycles up and down without load or no cycling of the pump under load. If you are unsure, remove the fluid pump from the motor and test. Make sure the oil in the hydraulic pump is at the correct level and the hydraulic ball valve on the side of the hydraulic motor is open.

Please refer to the correct user manual for your model machine.

Graco Part No. 246174

Visit our product download centre for manuals & spare parts

## **Additional Information**

Brands	Graco
Equipment Type	Airless Sprayers, Line Marking Machines
Machine Type	Petrol
Machine Model Number	GH130, GH200, GH230, GH300, 200HS LineLazer V, 250DC LineLazer V, 250SPS LineLazer V, 130HS LineLazer IV, 130HS LineLazer IV, 250SPS LineLazer IV
OEM	Original Part

