




# Graco 248215 Kit Repair Intake Tube

**\$105.27**  
**INCL. GST**

## Product Images



## Short Description

Graco 248215 Kit Repair Intake Tube is used on most Graco GMax II 5900, 5900HD, 7900 & 7900HD Hi-Boy Petrol models from about 2004 onwards. Intake tube includes the 118494 O-ring that is fitted to the male thread of the intake valve housing.

## Description

Graco 248215 Kit Repair Intake Tube is used on most Graco GMax II 5900, 5900HD, 7900 & 7900HD Hi-Boy Petrol models from about 2004 onwards. Intake tube includes the 118494 O-ring that is fitted to the male thread of the intake valve housing.

Length of the tube is 186mm and uses a [1" Suction Filter](#)

**Graco 248215 Kit Repair Intake Tube is used on the following models –**

- 1095 UltraMax II Hi-Boy (Part No. 248051)
- 5900 GMax II Petrol Hi-Boy
- 5900HD GMax II Petrol Hi-Boy
- 7900 GMax II Petrol Hi-Boy
- 7900HD GMax II Petrol Hi-Boy
- 

Graco Part No. 248215

[Visit our product download centre for manuals & spare parts](#)

## Additional Information

Brands	Graco
Equipment Type	Airless Sprayers
Machine Type	Electric 240V, Petrol
Machine Model Number	Pilot K-100, 1095 UltraMax II, 5900 GMax II, 7900 GMax II, 5900HD Gmax II, 7900HD Gmax II
OEM	Original Part

