



Graco 245065 Replacement PTFE Diaphragm Repair Kit Triton 308

\$386.00
INCL. GST

Product Images



Short Description

Graco 245065 Replacement PTFE Diaphragm Repair Kit will suit all Triton 308 Double Diaphragm Pumps including stand, wall, trolley and drum mount versions. This kit includes both composite diaphragms and four check ball nylon seals.

Description


Graco 245065 Replacement PTFE Diaphragm Repair Kit will suit all Triton 308 Double Diaphragm Pumps including stand, wall, trolley and drum mount versions. This kit includes both composite diaphragms and four check ball nylon seals.

Graco 245065 Replacement Diaphragm Kit Includes -

- 2 x 197648 Diaphragm PTFE Composite
- 4 x 197666 Seal, Ball Check, Nylon

Graco 245065 Replacement Diaphragm Kit will suit -

- Part No. [233500](#) Aluminum Pump, Series D, npt threads
- Part No. [233501](#) Stainless Steel Pump, Series C, npt threads
- Part No. [233776](#) Aluminum Pump, Series C, BSPP threads
- Part No. [233777](#) Stainless Steel, Series C, BSPP threads



Atomex Part No. AX/G246-065

Replaces Graco Part No. 245065

[Click here to view all Graco Triton 308 Parts](#)

Additional Information

Brands	Graco
Equipment Type	Double Diaphragm Pumps
Machine Type	Pneumatic
Machine Model Number	Triton 308
OEM	Aftermarket

