



Atomex X-360 Airless Spray Gun Repair Kit

\$174.90
INCL. GST

Product Images



Short Description

Atomex AX/02-360-500 Airless Spray Gun repair kit for Atomex X-360 & X-380 airless spray guns. Made in the USA.

Description

Airless spray guns will require periodic service, over time and after many trigger pulls the carbide ball at the end of the needle will wear against seat on the diffuser. This will cause paint to leak or spit from the tip when you let go of the trigger.

Replacing the needle and diffuser (gun kit) is a normal part of airless sprayer maintenance and should be done as required. Keep a spare kit in your tool box to reduce down time on the job.

Gun Repair Kit will suit the following model guns –

Atomex X-360: , AX/02-360-000, AX/02-360-001, AX/02-360-002, AX/02-360-003

Atomex X-380: , AX/02-380-000

Atomex Part No. AX/02-360-500

This gun repair kit will fit into guns that look like this



Additional Information

Brands	Atomex
Equipment Type	Airless Sprayers
Machine Type	Airless Spray Guns
Machine Model Number	Atomex X-360 Airless Spray Gun
OEM	Original Part

