



Graco 257103 HVLP Turbine Gun Repair Kit

\$145.20
INCL. GST

Product Images



Short Description

Graco 257103 HVLP Turbine Gun Repair Kit for old Graco HVLP Turbine Spray Guns used with Graco Turbine Models 2500, 3800 & 4900

Description

Graco 257103 HVLP Turbine Gun Repair Kit for old Graco HVLP Turbine Spray Guns models 244113, 244117, 244115 & 244118.

Graco 257103 HVLP Turbine Gun Repair Kit includes –

- Part No. 111137 1 x Packing o-ring
- Part No. 188493 1 x Packing u-cup
- Part No. 188494 1 x Spreader u-cup
- Part No. 188495 1 x Packing u-cup
- Part No. 192352 1 x Screw packing
- Part No. 196438 1 x Spacer packing
- Part No. 196466 1 x Tube air cup
- Part No. 197457 1 x Label instruction
- Part No. 243842 1 x Valve air
- Part No. 244135 1 x Check valve 5 pack
- Part No. M70424 1 x Cup gasket

Graco Part No. GA/257103

AA Spray stock a full range of Graco HVLP guns, fluid sets, check valves, filters and hoses to suit all models of Graco HVLP Turbine Sprayers with fast delivery Australia wide.

Additional Information

Brands	Graco
Equipment Type	HVLP Turbines
Machine Type	Electric 240V
Machine Model Number	HVLP Turbine Gun
OEM	Original Part

