



Graco 288471 Replacement Pump Repair Kit

Regular Price

\$231.09 Special
Price

\$207.98

INCL. GST

Product Images



Short Description

Graco 288471 Replacement Pump Repair Kit will suit Graco GH130 airless sprayers and LineLazer 130HS line marking machines. Service kit includes all seals, v-packings and balls to service the fluid pump.

Description

Graco 288471 Replacement Pump Repair Kit includes all seals, v-packings and balls to service the fluid pump. Precision made in the USA.

Graco 288471 Replacement Pump Repair Kit will suit Graco GH130 airless sprayers and LineLazer 130HS line marking machines.

Please note – This packing repair kit has three leather packing vee's for the upper packing seals at the top of the pump but the packing seals on the piston rod use the new brown packing vee's. Please refer to the [24B748 pump manual](#) if you are unsure.

Precision made in the USA.

Atomex Part No. AX/G288-471

Replaces Graco Part No. 288471

Additional Information

Brands	Graco
Equipment Type	Airless Sprayers, Line Marking Machines
Machine Type	Petrol
Machine Model Number	GH130, 130HS LineLazer IV, 130HS LineLazer V
OEM	Aftermarket

