



Graco 249028 Replacement Piston Rod

\$665.45
INCL. GST

Product Images



Short Description

Graco 249028 Replacement Piston Rod will suit Graco Mark V TexSpray airless sprayers and Gmax II 5900HD petrol airless sprayers. Precision made in the USA.

Description

Graco 249028 Replacement Piston Rod will suit Graco Mark V TexSpray airless sprayers and Gmax II 5900HD petrol airless sprayers.

When replacing packing seals on your pump inspect the piston rod for wear, the piston rod shaft must be true, straight and have no wear marks, ripples or elongated scratches. Any wear or damage to the piston may cause the pump to leak externally or internally and will certainly reduce the life of your new packing seals.

Graco 249058 Replacement Piston Rod can only be used in pumps with the standard pin connection at the end of the rod. Not suitable for the recent Pro-Contractor models but this rod can be used in some of the older Mark V models such as 258888 and 249907.

Precision made in the USA.

Atomex Part No. AX/G249-028

Replaces Graco Part No. 249028

[Visit our product download centre for manuals & spare parts](#)

Additional Information

Brands	Graco
Equipment Type	Airless Sprayers, Line Marking Machines
Machine Type	Electric 240V, Petrol
Machine Model Number	5900HD Gmax II, Mark V TexSpray
OEM	Aftermarket

