



Wagner 0279911 Maxum Elite HVLP Gun Repair Kit

\$85.00
INCL. GST

Product Images



Short Description


Wagner 0279911 Maxum Elite HVLP Gun Repair Kit includes minor service and replacement parts for routine strip down and maintenance of your Maxum Elite HVLP spray gun.

Description

Wagner 0279911 Maxum Elite HVLP Gun Repair Kit includes minor service and replacement parts for routine strip down and maintenance of your Maxum Elite HVLP spray gun.

Wagner 0279911 Maxum Elite HVLP Gun Repair Kit includes the following items -

- Item 6 - 0275501 Rear air valve seal
- Item 9 - 0277486 Air valve seal
- Item 16 - 0508403 Air flow valve o-ring
- item 35 - 0524503 Gun head seal
- Item 38 - 0524618 Gun body o-ring
- Item 42 - 0275579 Needle packing
- Item 43 - 0529220 Check valve retainer assembly
- Item 45- 0276415 Check valve seal
- Item - 0277495 Cup gasket (Suction cup only)



Wagner 0279911 Maxum Elite HVLP Gun Repair Kit used with the following models -

Titan Wagner Maxum Elite HVLP Gun

Wagner Part No. 0279911

[Visit our product download centre for manuals & spare parts](https://airless.com.au/wagner-0279911-maxum-elite-hvlp-gun-repair-kit.html)

Additional Information

Brands	Wagner
Equipment Type	HVLP Turbines
Machine Type	Electric 240V
Machine Model Number	Maxum Elite
OEM	Original Part

