



Binks 0115-010037 AX85S Poppet Assembly Kit

\$190.57
INCL. GST

Product Images



Short Description

Binks 0115-010037 AX85S Poppet Assembly kit will suit both MX432 & MXL432 pneumatic airless sprayers. Air motor requires two poppet assemblies for each end of the air motor, two poppets are contained in this kit.


Description

Binks 0115-010037 AX85S Poppet Assembly kit (2 Valves) will suit both MX432 & MXL432 pneumatic airless sprayers. Air motor requires two poppet assemblies for each end of the air motor.

Binks 0115-010037 AX85S Poppet Assembly is also available in the [0115-010215](#) AX-85 Air Motor Repair Kit.

Binks 0115-010037 AX85S Poppet Assembly is used on the following models -

- Binks AX-85 Air Motor
- Binks MX432 Airless Sprayer
- Binks MXL432 Airless Sprayer



- Parts are included in 0115-010215 AX85 Repair Kit.
- ◇ Parts are included in 0115-010217 AX85 Seal Kit.
- Parts are included in 0115-010226 Air Motor Valve Repair Kit.

Binks Part No. 0115-010037

[Click here to see the full range of Binks MXL432 spare parts](https://airless.com.au/binks-0115-010037-ax85s-poppet-assembly.html)

Additional Information

Brands	Binks
Equipment Type	Airless Sprayers
Machine Type	Pneumatic
Machine Model Number	MX432, MXL432
OEM	Original Part

