



# Graco 156633 Replacement Packing O- Ring

**\$18.71**  
**INCL. GST**

## Product Images



## Short Description

---

Graco 156633 Replacement Packing O-Ring is widely used throughout the Graco range of equipment including Ultra Max II 1095/Mark V and Gmax II 5900 airless sprayers.


## Description

---

Graco 156633 Replacement Packing O-Ring is widely used throughout the Graco range of equipment including Ultra Max II 1095/Mark V and Gmax II 5900 airless sprayers.

The 156953 Packing O-Ring is located between the end of the pump cylinder and the intake housing typically used on Graco Ultra Max II 1095/Mark V electric airless sprayers, Gmax II 5900 petrol airless sprayers and 5900 line markers.

Location of 156633 Packing O-Ring in a 1095/5900 pump -



People commonly replace this o-ring when they have a leak at the foot valve but this o-ring will not fix this problem. You should consider replacing the 107098 packing o-ring which is located at the end of the pump sleeve and consult the user manual for your machine.

Atomex Part No. AX/G156633

Replaces Graco Part No. 156633

---

[Visit our product download centre for manuals & spare parts](#)

## Additional Information

---

Brands	Graco
Equipment Type	Airless Sprayers
Machine Type	Electric 240V, Petrol
Machine Model Number	1095 UltraMax II, 5900 GMax II, ES2000 LineLazer V, 5900 LineLazer IV, 5900HD Gmax II, Mark V TexSpray
OEM	Aftermarket

