




# Graco 288817 SG2/SG3 Airless Spray Gun Repair Kit OEM

\$156.20 Special Price
\$140.58
INCL. GST

#### **Product Images**



# **Short Description**

Graco Part No. 288817 Airless Spray Gun repair kit for Graco SG2 & SG3 airless spray guns.

### **Description**

Airless spray guns will require periodic service, over time and after many trigger pulls the carbide ball at the end of the needle will wear against seat on the diffuser. This will cause paint to leak or spit from the tip when you let go of the trigger.

Replacing the needle and diffuser (gun kit) is a normal part of airless sprayer maintenance and should be done as required. Keep a spare kit in your tool box to reduce down time on the job.

#### Graco 288817 Gun Repair Kit will suit the following model guns -

243011, 243012, 246506, 243238, 243382, 289843, 257359, 16W431, 16X214, 17J910

Graco Part No. 288817

This gun repair kit will fit into guns that look like this



# **Additional Information**

Brands	Graco
Equipment Type	Airless Sprayers
Machine Type	Airless Spray Guns
Machine Model Number	SG2 & SG3 Gun
OEM	Original Part

