



# Graco 222848 Replacement Pump Repair Kit For Dura-Flo 1800 Pumps

Regular Price

**\$690.34** Special  
Price

**\$621.30**

**INCL. GST**

## Product Images



## Short Description

---

Graco 222848 Replacement Pump Repair Kit is suitable for Graco Dura-Flo 1800 430cc pump lowers. Service kit includes UHMWPE/Leather upper/lower packing seals, upper/lower stainless steel balls and teflon sealing rings.

## Description

---

Graco 222848 Replacement Pump Repair Kit is suitable for Graco Dura-Flo 1800 430cc pump lowers. Service kit includes UHMWPE/Leather upper/lower packing seals, upper/lower stainless steel balls and teflon sealing rings.

Graco 222848 Replacement Pump Repair Kit is suitable for Graco Dura-Flo 1800 430cc pump lowers. Service kit includes UHMWPE/Leather upper/lower packing seals, upper/lower stainless steel balls and teflon sealing rings.

**Graco 222848 Replacement Pump Repair Kit can be used in the following pumps –**

D1800 Stainless Steel Pump 430cc

222796 Carbon Steel Pump 430cc

24W644 Carbon Steel Pump 430cc

222988 Carbon Steel Pump 430cc

222805 Stainless Steel Pump 430cc

L430CS Carbon Steel Pump 430cc

L430SS Stainless Steel Pump 430cc

Graco 222848 Replacement Pump Repair Kit can be used in both carbon steel and stainless steel pumps. The combination of UHMWPE/Leather seals gives the highest wear resistance in both waterborne and solvent based materials especially on paints that contain debris and higher solids and is also suited for line marking trucks that have heated paint systems.

Atomex Part No. AX/G222-848

Replaces Graco Part No. 222848

Can be used in place of Graco Part No. 222849

---

[Visit our product download centre for manuals & spare parts](#)

## Additional Information

Brands	Atomex, Graco
Equipment Type	Line Marking Machines
Machine Type	Hydraulic
Machine Model Number	Dura-Flo 1800 430cc
OEM	Aftermarket

