



Graco 222875 Replacement Pump Repair Kit For Dura-Flo 2400 Pumps

Regular Price

\$592.10 Special
Price

\$532.88

INCL. GST

Product Images



Short Description

Graco 222875 Replacement Pump Repair Kit is suitable for Graco Dura-Flo 2400 580cc pump lowers. Service kit includes UHMWPE/PTFE upper/lower packing seals and teflon sealing rings.

Description

Graco 222875 Replacement Pump Repair Kit is suitable for Graco Dura-Flo 2400 580cc pump lowers. Service kit includes UHMWPE/PTFE upper/lower packing seals and teflon sealing rings.

Graco 222875 Replacement Pump Repair Kit is suitable for Graco Dura-Flo 2400 580cc pump lowers. Service kit includes UHMWPE/PTFE upper/lower packing seals and teflon sealing rings. Kit does not include upper or lower balls, these will need to be purchased separately.

Graco 222875 Replacement Pump Repair Kit can be used in the following pumps -

D2400 Carbon Steel Pump 580cc

222801 Carbon Steel Pump 580cc

222991 Carbon Steel Pump 580cc

222992 Carbon Steel Pump 580cc

222803 Stainless Steel Pump 580cc

222993 Stainless Steel Pump 580cc

222994 Stainless Steel Pump 580cc

236226 Stainless Steel Pump 580cc

236230 Stainless Steel Pump 580cc

L580CS Carbon Steel Pump 580cc

L580SS Stainless Steel Pump 580cc

Graco 222875 Pump Repair Kit can be used in both carbon steel and stainless steel pumps.

Atomex Part No. AX/G222-875

Replaces Graco Part No. 222875

[Visit our product download centre for manuals & spare parts](#)

Additional Information

Brands	Atomex, Graco
Equipment Type	Line Marking Machines
Machine Type	Hydraulic
Machine Model Number	Dura-Flo 2400 580cc
OEM	Aftermarket

