




Graco 287206 Kit Repair Suction Hose

\$915.20
INCL. GST

Product Images



Short Description

Graco 287206 Kit Repair Suction Hose for Graco LineLazer III 200HS & LineLazer IV 130HS/200HS line marking machines. Complete suction hose assembly including return hose and suction strainer.

Description

Graco 287206 Kit Repair Suction Hose is used on the following models -

Graco LineLazer III 200HS


Graco LineLazer IV 130HS

Graco LineLazer IV 200HS

Graco LineLazer IV 200HS Auto-Layout

Graco 287206 Kit Repair Suction Hose includes the following items -

- Item 34a - 15F149 Tube, suction
- Item 34b - 194306 Hose, fluid
- Item 34c - 198119 Elbow, barbed
- Item 34d - 101818 Clamp, hose
- Item 34e - 181072 Strainer, inlet
- Item 34f - 198601 Tube, drain
- Item 34g - 241920 Deflector, threaded
- Item 34h - 248008 Hose, coupled ¼" x 4 ft
- Item 34j - 114958 Strap, tie
- Item 34k - 196180 Bushing
- Item 34N - 278722 Pail, gasket



Visit our product download centre for manuals & spare parts

Additional Information

Brands	Graco
Equipment Type	Line Marking Machines
Machine Type	Petrol
Machine Model Number	130HS LineLazer IV, 200HS LineLazer IV
OEM	Original Part

