




# Graco 245730 Kit Repair Suction Hose

**\$915.20**  
**INCL. GST**

## Product Images



## Short Description

Graco 245730 Kit Repair Suction Hose for Graco LLIII 3900/5900 & LLIV 3900/5900 line marking machines. Complete suction hose includes drain hose and suction filter.

## Description

---


Graco 245730 Kit Repair Suction Hose for Graco LLIII 3900/5900 & LLIV 3900/5900 line marking machines.

### **Graco 245730 Kit Repair Suction Hose is used on the following models –**

- Graco LineLazer LLIII 3900
- Graco LineLazer LLIII 5900
- Graco LineLazer LLIV 3900
- Graco LineLazer LLIV 5900
- Graco LineLazer LLIV 5900 Auto-Layout

### **Graco 245730 Kit Repair Suction Hose includes the following items –**

- Item 12a – 170957 Replaced with [15F149 Tube, suction](#)
- Item 12b - [185381 Hose](#)
- Item 12c - [110194 Fitting, union swivel 180 degree](#)
- Item 12d - [101818 Clamp, hose](#)
- Item 12e - [193711 Gasket, pail \(Replaced with 15F513\)](#)
- Item 12f - [181072 Strainer](#)
- Item 12g - 245731 Tube, drain (includes diffuser)
- Item 12h - Diffuser
- Item 12j - [245798 Hose, coupled ¼" x 7'](#)
- Item 12k - 114958 Strap, tie
- Item 12m - [196180 Bushing](#)



Graco Part No. 245730

[Visit our product download centre for manuals & spare parts](https://airless.com.au/graco-245730-kit-repair-suction-hose.html)

## Additional Information

---

Brands	Graco
Equipment Type	Line Marking Machines
Machine Type	Petrol
Machine Model Number	3900 LineLazer IV, 5900 LineLazer IV
OEM	Original Part

